

1st Boys

SURVEY REPORT OF SCHOOLS TOILET UNDER "SWACHHA VIDYALAYA ABHIYAN" CONDUCTING

BY KANIHA AREA, TALCHER COALFIELDS, MCL

District: - Rayagada

Block: - MUNIQUUDA.

Village:- RAGHUBARI

School Name:- RAGHUBARI UPS

School Code:- 21270828801

No. of Student:- 152

Girls:- 57

Boys:- 95

Status of toilet:-

Existing:- ONE NR TOILET

Not existing:-

Toilet Requirement:-

UNDER CONSTRUCTION.

Boys:-

If Existing:-

Sl no.	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC	NA.	
2	Urinals	NA.	
3	Doors(Size)	Steel door - INS - Good p. 75x1.50	
4	Floor level	NA.	
5	Wall level	B.Wall - Good.	
6	Internal Plaster	Good	
7	Outer plaster	Good.	
8	Inspection Chamber	NA.	
9	Lease Pit/Septic tank	NA.	

Source of Water

Bore well with pump NA /

Hand pump / NO (DANGEROUS)

Water tank

Ground NA /

Overhead NA.

Water tank Capacity

Remarks if any: The toilet is under construction. Roof slab already done.


 HEAD MASTER
 Sign of School Head Master
 Govt. U.G. High School
 Raghubari, Dist. Puri


 Sign of School Mgt Committee
 Chairperson SMC
 Govt. U.G. High School
 Raghubari, Dist. Rayagada


 Sign of Surveyor
 SOFC, KA

Name Surendra Kumar Mishra Name Pratik Panda School

Name Subash Ch Nanda.

Email ID

Email ID

Email ID Subashnanda @

Ph.No. 8270455064

Ph.No.

Ph.No. 9488878808