

S.I. No. - 191

GIRLS

SURVEY REPORT OF SCHOOLS TOILET UNDER "SWACHHA VIDYALAYA ABHIYAN" CONDUCTING

BY KANIHA AREA, TALCHER COALFIELDS, MCL

District: - Rayagada

Block: - Muni guda

Village:- 21270825701

School Name: -

RAJULUGUDA N.P.S

School Code:-

No. of Student: -

27 Girls: - 11

Boys:- 16

Status of toilet: -

Existing:- Yes (01 - Good
02 - Damaged)

Not existing:-

Toilet Requirement: -

Boys:-

If Existing:-

Sl no.	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC	Yes	
2	Urinals	Yes	
3	Doors(Size)	Sked.Dna, 1.05 X 1.80 0.89 X 1.80, 0.74 X 1.80	
4	Floor level	Tilr	
5	Wall level	Brick work	
6	Internal Plaster	Yes	
7	Outer plaster	Yes	
8	Inspection Chamber	NA	
9	Lease Pit/Septic tank	Yes	

Source of Water

Bore well with pump NA / Hand pump 01 NA

Water tank

Ground NA / NA Overhead

Water tank Capacity

Remarks if any:

Satyanarayan Sundarany x
HeadmasterPrimary School
Sign of School Headmaster
Rajuluguda, MungudaS. M. C. P. S. Rajuluguda
Sign of School M.S.T. Committee
RajulugudaSignature
Sign of Surveyor

Name

Satyanarayan
Sundarany

Name

Tapas Ranjan Pradho

Email ID

Email ID

Email ID

Ph.No.

9776551119

Ph.No.

Ph.No. 9938631916