

Sl. No. 199

GIRLS

**SURVEY REPORT OF SCHOOLS TOILET UNDER "SWACHHA VIDYALAYA ABHIYAN" CONDUCTING BY KANIHA AREA, TALCHER COALFIELDS, MCL**

District: - Rayagada

Block: - MDNI GUDA -

Village:- SILIKUDI

School Name: - SILIKUDI P.S

School Code:- 2127082910

No. of Student: - 37

Girls: - 19

Boys:- 18

Status of toilet: -

Existing: - NA

Not existing:- ✓

Toilet Requirement:-

Girls: -

Boys:-

If Existing:-

Sl no.	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC		
2	Urinals		
3	Doors(Size)		
4	Floor level		
5	Wall level		
6	Internal Plaster		
7	Outer plaster		
8	Inspection Chamber		
9	Lease Pit/Septic tank		

~~NO TOILET EXISTS IN SCHOOL~~

Source of Water

Bore well with pump NA /

Hand pump NA.

Water tank

Ground NA /

Overhead NA.

Water tank Capacity

Remarks if any:



*R. Pathan.*

Sign of School Head Master

Sign of School Mgt Committee

*S. Nanda*

Silikudi Primary School

Sign of Surveyor S of C, KA.

Head Master.

Silikudi Primary School

Name KSHITRA SINDHU PATHAN

Name Sabitree Joud -

Name Subash Ch Nanda.

Email ID

Email ID

Email ID subashnanda@gmail.com

Ph.No. 8658204863

Ph.No.

Ph.No. 9488878808