

(13)

"स्वच्छ भारत अभियान"

DISTRICT: GAJAPATI BLOCK: NUAGADA VILLAGE: RAJAPUR
 SCHOOL NAME: NPS RAJAPUR SCHOOL CODE:
 NO. OF STUDENT: 32 GIRLS: 12 BOYS: 20
 STATUS OF TOILET: NIL EXISTING:
 TOILET REQUIREMENT: GIRLS: 02 BOYS: 02
 If EXISTING:

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	} N.A.	} New building for toilet are required of nos.
2	URINALS		
3	DOORS(SIZE)		
4	FLOOR LEVEL		
5	WALL LEVEL		
6	INTERNAL PLASTER		
7	OUTER PLASTER		
8	INSPECTION CHAMBER		
9	LEASE PIT/ SEPTIC TANK		

SOURCE OF WATER: NIL BORE WELL WITH PUMP:
 WATER TANK: NIL GROUND:
 WATER TANK CAPACITY: N.A. HAND PUMP:
 OVERHEAD:

Remarks If any: Neither teacher nor committee members were available. It is co-ordinated with the T.O of Education dept of Nuagade block. It is a new school of 2014 having no building of 100 toilets are hand pump

Sign of School Head Master Sign of School Mgt Committee Sign of Surveyor
 NAME: Niranjan Kasgi NAME: N.A. NAME: 23/1/15

Abinash Kumar Sahu
Technical Consultant
Nuagada Block