

Date - 30.01.15. (34)

"स्वच्छ भारत अभियान"

DISTRICT: NAYAGARI

BLOCK: NUAHOAN

VILLAGE: Kandhakhalamada.

SCHOOL NAME: Kandhakhalamata PS

SCHOOL CODE: 607301

NO. OF STUDENT: 20

GIRLS: 10

BOYS: 10

STATUS OF TOILET:

EXISTING: YES

NOT EXISTING:

TOILET REQUIREMENT:

GIRLS: YES

BOYS: YES.

IF EXISTING:

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	X	Need new construction
2	URINALS	X	do
3	DOORS(SIZE)	✓	Need to repair
4	FLOOR LEVEL	X	do
5	WALL LEVEL	✓	do
6	INTERNAL PLASTER	X	do
7	OUTER PLASTER	X	do
8	INSPECTION CHAMBER	X	need to construct
9	LEASE PIT/ SEPTIC TANK	X	do

for both boys & girls

SOURCE OF WATER:

BORE WELL WITH PUMP: NO

HAND PUMP: YES

WATER TANK:

GROUND: NO

OVERHEAD: NO

WATER TANK CAPACITY:

Remarks If any: 1. Need to construct new toilets and urinals for both boys and girls, as existing structure is totally damaged.

2. Need to give other source of water. Existing source is not working properly.

Sign of School Head Master

Sign of School Mgt Committee

Sign of Surveyor

Headmaster
Kandhakhalamada Pry. School

NAME: Nimee Chaman Sabh

NAME: Geetanjali Pradhan

NAME: Varun Kumar

Varun Kumar
S. S. Pathanagar