

"स्वच्छ भारत अभियान"

DISTRICT: NAYAGARH BLOCK: NUAGOAN VILLAGE: RADHANATHPUR
 SCHOOL NAME: RADHANATHPUR PS SCHOOL CODE: 600801
 NO. OF STUDENT: 28 GIRLS: 15 BOYS: 13.
 STATUS OF TOILET: EXISTING: YES. NOT EXISTING:
 TOILET REQUIREMENT: GIRLS: BOYS:
 If EXISTING:

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	(1) one	Need to repairs (one)
2	URINALS	1 (one)	— do —
3	DOORS(SIZE)	✓	— do —
4	FLOOR LEVEL	✓	— do —
5	WALL LEVEL	✓	— do —
6	INTERNAL PLASTER	✓	— do —
7	OUTER PLASTER	✓	— do —
8	INSPECTION CHAMBER	X	Need to construct
9	LEASE PIT/ SEPTIC TANK	X	Need to repairs

SOURCE OF WATER: PHD Connection BORE WELL WITH PUMP: HAND PUMP: YES
 WATER TANK: GROUND: OVERHEAD: YES.
 WATER TANK CAPACITY: 450 Lit
 Remarks If any: Need to repairs ~~toilet~~ toilet and Urinal structure for boys.

for Bzavik,
 Sign of School Head Master
 H.M -Cum- Convener
 S.M.C. Radhanathpur P.S. School
 NAME: Bhagaban Barik

महोदय, शादी होना
 Sign of School Mgt Committee
 S.M.C
 Chair
 Radhanathpur Primary School
 NAME:

Vasim
 Sign of Surveyor
 NAME: Vasim Kumar

महोदय, शादी होना
 S.S. Pattanayak