

12-01-2015

District Dhenkanal Block Colepada Village Manpura
 School Name Manpura Primary School School Code 21140210803
 No. of Student Girls- 70 Boys- 70
 Status of toilet Existing 01 Not Existing
 Toilet Requirement Girls 01 Boys 01

If Existing:

Sl.No	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC		<u>02 Nil</u>
2	Urinals	<u>NIL</u>	
3	Doors (size)	<u>0.92 x 1.50, 0.60 x 1.52</u> <u>0.60 x 1.20</u>	
4	Floor level	<u>+0.05</u> <u>+0.50</u>	
5	Wall level	<u>+1.93</u>	
6	Internal plaster	<u>Good</u>	
7	Outer plaster	<u>fair</u>	
8	Inspection Chamber	<u>NIL</u>	
9	Lease pit / septic tank	<u>01</u>	

Source of Water Bore well with pump / Hand pump (Inadequate water discharge)
 Water tank Ground / Overhead NIL
 Water tank Capacity NA

Remarks if any: Used open well available having hard water. As no urinals available and toilets defunct hence recommended to construct both toilets.

Sign of School head master

Haribansamal
 Name
 Headmaster
 Manapur Primary School
 Dhenkanal

Cell. 9437415232

Sign of School Mgt Committee

Name

Sandeep
 Sign of Surveyor
12-01-15
S.K. Mishra
 SOER

Name

9438879727

Mishra
SOER