

08  
12-01-2015 (4)

District Dhenkanal Block Odapada Village Ranja Singh  
 School Name Ranjasingha Binery School School Code 21140711401  
 No. of Student Girls- 30 Boys- 41  
 Status of toilet Existing 01 Not Existing  
 Toilet Requirement Girls - Boys 01

If Existing:

| Sl.No | Item                    | Condition                               |                        |
|-------|-------------------------|---|------------------------|
|       |                         | Good in Nos.                            | To be replaced in Nos. |
| 1     | WC                      | <u>01</u>                               |                        |
| 2     | Urinals                 | <u>NIL</u>                              |                        |
| 3     | Doors (size)            | <u>NIL</u>                              |                        |
| 4     | Floor level             | <u>+0.25</u>                            |                        |
| 5     | Wall level              | <u><math>\frac{1.80+1.50}{2}</math></u> |                        |
| 6     | Internal plaster        | <u>Good</u>                             |                        |
| 7     | Outer plaster           | <u>Good</u>                             |                        |
| 8     | Inspection Chamber      | <u>NIL</u>                              |                        |
| 9     | Lease pit / septic tank | <u>NIL</u>                              |                        |

Source of Water Bore well with pump /  Hand pump  
 Water tank Ground /  Overhead Not available  
 Water tank Capacity NA

Remarks if any: Girls toilet under const<sup>n</sup>. (Savva sikhya Abhiyan).  
 Recommended for const<sup>n</sup> of boys toilet

Minati Nayak  
 Sign of School head master  
9668999642

Sign of School Mgt Committee

Sudhane  
 Sign of Surveyor  
12-01-15  
S.K. Mishra  
8438879722  
 MT (CD)

Name **Headmaster**  
**Ranjasingha Pry. School**  
**Dhenkanal**

Name

Name

Mishra  
12/01/15