

16-01-2015

District Dhemandel Block Odapada Village Sadasivpur.
 School Name Sadasivpur Nuasahi P-2 School Code 21140714101
 No. of Student Girls- 06 Boys- 14
 Status of toilet Existing - 01 Not Existing
 Toilet Requirement Girls Boys - 01

If Existing:

Sl.No	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC	<u>01</u>	
2	Urinals	<u>NIL</u>	
3	Doors (size)	<u>1x 1.64x 0.60</u> <u>2x 1.42x 0.60</u>	
4	Floor level	<u>+ 0.15</u>	
5	Wall level	<u>2.00</u>	
6	Internal piaster	<u>Good</u>	
7	Outer plaster	<u>Good</u>	
8	Inspection Chamber	<u>NIL</u>	
9	Lease pit / septic tank	<u>—</u>	<u>01 (defunct)</u>

Source of Water Bore well with pump / Hand pump

Water tank Ground / Overhead

Water tank Capacity $\frac{\pi}{4} \times (0.70)^2 \times 0.80$

Remarks if any: No urinals available. Both Boys and girls toilets may be constructed.

Sign of School head master
Aparna Kumar Hota
 Ph. 9438271346

Sign of School Mgt Committee

[Signature]
16-01-15
 Sign of Surveyor
[Signature]
 C.M.C., BA
 M.T.-C.D.

Name [Signature]
16-1-15
 Headmaster

Name

Name

[Signature]
16/1/15