

District Kandhamal Block Phiringia Village - Balkudadi
 School Name Balkudadi P.S School Code _____
 No. of Student 39 Girls- 14 Boys- 25
 Status of toilet Existing 1 set - used by girls & boys Not Existing _____
 Toilet Requirement Not required Girls 1 Under construction for girls Boys _____
 If Existing: _____

Sl.No	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC	01	
2	Urinals	02	
3	Doors (size)	0.75 X 1.70	
4	Floor level	Zero	
5	Wall level	1.80	
6	Internal plaster	✓	
7	Outer plaster	✓	
8	Inspection Chamber	X	
9	Lease pit / septic tank	X	

Source of Water Bore well with pump / Hand pump Dry during summer
 Water tank Not available Ground / Overhead
 Water tank Capacity _____

Remarks if any: No electricity, Toilet not required as no. of students are less and a new set of toilet is under construction.

[Signature]
HEADMASTER
 School of P. School

[Signature]
 Sign of School Mgt Committee

[Signature]
 Sign of Surveyor

Peena Chandra Kanhar
 Name
9439073093

John Bodra
 Name

[Signature]