

District **Kandhamal** Block **Phiringia**

Village **Kasinipadar**

School Name **Barebata PS**

School Code **21210810901**

No. of Student **34**

Girls- **23**

Boys- **11**

Status of toilet

Existing - 1 ~~Block~~
(common)

Not Existing

Toilet Requirement

Girls

Boys - 1

If Existing:

| Sl.No | Item | Condition | |
|-------|-------------------------|-----------------------------|------------------------|
| | | Good in Nos. | To be replaced in Nos. |
| 1 | WC | | 1 |
| 2 | Urinals | 1-6 4 | |
| 3 | Doors (size) | -6m x 1.2m (2) -6m x 1.5 | |
| 4 | Floor level | 0.3m | |
| 5 | Wall level | 1.8m 1.8m | |
| 6 | Internal plaster | Fully damaged | |
| 7 | Outer plaster | " | |
| 8 | Inspection Chamber | NIL | |
| 9 | Lease pit / septic tank | NIL | |

Source of Water

Bore well with pump / Hand pump

Water tank **NIL**

Ground / Overhead

Water tank Capacity

Remarks if any:

- No electricity connection
- one toilet block is under construction.

Signature of Headmaster
Headmaster

Signature of School Mgt Committee
Manorama Behera

Signature of Surveyor
Rohith MR

**Primary School
Barebata**

Name **Brajraj Kanhoj**

Name **Manorama Behera**
Dt-13-2-2015

Rohith MR

M.No- 9897 3288 3A

[Handwritten signature]