

District: KANDHAMAL

Block: PHULBANI

Village: KEREDI G.P.

Schools Name: DANGULI UPS

No. of students: 87

School Code: 21210917201

Status of Toilets:  Exists/ Non-Exists

Boys: 39

Girls: 48

No. of Toilets Required:

No. of Boys Toilet: |

No. of Girls Toilet: |

CWSN: |

Boys: |

Girls: |

Specification of Toilets:

Sl No.	Items	Goods in Nos.	Specification of Goods	Replaceable in nos.	Remarks
01	WC Commode	2			good condition
02	Urinals	-	Boys:                  Girls:		
03	Doors		Type: <input checked="" type="checkbox"/> Steel/ <input checked="" type="checkbox"/> PVC/ <input type="checkbox"/> Wood Size: 3' x 2' x 6'		
04	Flooring		Tiles: <input checked="" type="checkbox"/> Concrete:		
05	Wall Level Flooring		Height: 8'                  Tile: <input checked="" type="checkbox"/> Concrete:		
06	Internal Plaster		CP: <input checked="" type="checkbox"/> Other:		
07	External Plaster		CP: <input checked="" type="checkbox"/> Other:		
08	Inspection Camber		Exists:                  Not-Exists: <input checked="" type="checkbox"/>		
9	Lease Pit/Septic Tank		Exists: <input checked="" type="checkbox"/> Not-Exists:		
10	Electricity		Available: <input checked="" type="checkbox"/> Not-Available:		
11	Drainage System		Available: <input checked="" type="checkbox"/> Not Available:		

well-damaged

Sources of Water:  Well/Well with pump/Bore well with pump/Hand pump or Tube well

Water Tank:  Concrete/PVC                  Overhead/Underground Tank                  Water Capacity:

Remarks or Suggestions if any: 1 number boys & one number girls toilet require

Sig. of School HM: *N. Nayak*                  Sig. of SMC

Sig. of TC: *b. bahoo*                  Sig. of Surveyor

Name: *Smt. Nabina Nayak*                  Name: *Buranya Bahoo*  
MB No: 9439207110                  Technical Consultant  
S.M.C. President                  Phulbani Block  
Dangulu U.P. School                  R.T.E. S.S.A. Kandhamal

*Chasey*  
*A. Nayak*