

District: KANDHAMAL

Block: PHULBANI

Village: KEREDI GPSchools Name: DEDIGUNDA PS

School Code: 21210917031

No. of students: 5Boys: 2Girls: 3Status of Toilets: Exists/ Non-ExistsNo. of Boys Toilet: 1No. of Girls Toilet: 1

CWSN:

No. of Toilets Required:

Boys: 1Girls: 1Specification of Toilets:

Sl No.	Items	Goods in Nos.	Specification of Goods	Replaceable in nos.	Remarks
01	WC Commode	<u>1</u>			
02	Urinals		Boys: <u>1</u> Girls: <u>1</u>		
03	Doors		Type: <input checked="" type="checkbox"/> Steel/ <input checked="" type="checkbox"/> PVC/ <input checked="" type="checkbox"/> Wood Size: <u>3x2'x6'</u>		
04	Flooring		Tiles: <input checked="" type="checkbox"/> Concrete:		
05	Wall Level Flooring		Height: <u>7'</u> Tile: <input checked="" type="checkbox"/> Concrete:		
06	Internal Plaster		CP: <input checked="" type="checkbox"/> Other:		
07	External Plaster		CP: <input checked="" type="checkbox"/> Other:		
08	Inspection Camber		Exists: Not-Exists: <input checked="" type="checkbox"/>		
9	Lease Pit/Septic Tank		Exists: <input checked="" type="checkbox"/> Not-Exists:		
10	Electricity		Available: Not-Available: <input checked="" type="checkbox"/>		
11	Drainage System		Available: Not Available: <input checked="" type="checkbox"/>		

Sources of Water: Well/Well with pump/Bore well with pump/Hand pump or Tube well

Water Tank: Concrete/PVC Overhead/Underground Tank Water Capacity:

Remarks or Suggestions if any: one girls toilet required

Sig. of School HM

Sig. of SMC

Sig. of TC

Sig. of Surveyor

Name: Rajani SharmaName: ଶ୍ରୀମତୀ ରଞ୍ଜନୀName: Buranya baho

Name:

Mb. No: 8895564950
**Primary School
Dedigunda**Mb. No: ୯୯୯୯୯୯୯୯Mb. No: ୯୯୯୯୯୯୯୯
**Technical Consultant
Phulbani Block
RTE-SSA, Kandhamal**A. D. D. D.