

District: KANDHAMAL

Block: PHULBANI MPL

Village:

Schools Name: KADAKATI NPS .

School Code: 21210915501

No. of students: 11

Boys: 7

Girls: 4

Status of Toilets: Exists/ Not Exists

Boys: 1

Girls: 1

CWSN:

No. of Toilets Required:

Boys: 1

Girls: 1

Specification of Toilets:

| Sl No. | Items | Goods in Nos. | Specification of Goods | | Replaceable in nos. | Remarks |
|--------|-----------------------|---------------|---|--|---------------------|---------|
| 01 | WC Commode | 1 | | | | |
| 02 | Urinals | 1 | Boys: 1 | Girls: 1 | | |
| 03 | Doors | | Type: Steel/ PVC/ Wood Size: 2' x 5' | | | |
| 04 | Flooring | | Tiles: | Concrete: <input checked="" type="checkbox"/> | | |
| 05 | Wall Level Flooring | | Height: 7' | Tile: Concrete: | | |
| 06 | Internal Plaster | | CCP: <input checked="" type="checkbox"/> | Other: | | |
| 07 | External Plaster | | CCP: <input checked="" type="checkbox"/> | Other: | | |
| 08 | Inspection Camber | | Exists: | Not-Exists: <input checked="" type="checkbox"/> | | |
| 9 | Lease Pit/Septic Tank | | Exists: <input checked="" type="checkbox"/> | Not- Exists: | | |
| 10 | Electricity | | Available: | Not-Available: <input checked="" type="checkbox"/> | | |
| 11 | Drainage System | | Available: | Not Available: <input checked="" type="checkbox"/> | | |

Sources of Water: Well/Well with pump/Bore well with pump/Hand pump or Tube well

not available of water.

Water Tank: Concrete/Fiber Overhead/Underground Tank

Water Capacity:

Remarks or Suggestions if any: One number boys and girl toilet required.

Rameshchandra Hota

Biswanidhi Dighr

S. Bahoo

Sig. of School HM

Sig. of SMC

Sig. of TC

Sig. of Surveyor

Name: Ramesh ch Hota

Name:

Name: hukanya bahoo

(Signature)
A. Prasad

Mb. No: 8895120560

Mb. No:
President

Technical Consultant
Phulbani Block
RTE-200, Phulbani, India

Headmaster

Kadakat N.P.S

Phulbani, Kandhamal

Kadakat N.P.S
Phulbani, Kandhamal