

District: KANDHAMAL

Block: PHULBANI

Village:

Kadali village  
(Jamuhari G.P.)

Schools Name: Kadali P.S.

School Code: 212109

No. of students: 28

Boys: 15

Girls: 13

Status of Toilets:  Exists/ Non-Exists

No. of Boys Toilet:

No. of Girls Toilet: \*

CWSN: \*

No. of Toilets Required: 01 (02)

Boys: 01 (02)

Girls: \*

Specification of Toilets:

Sl No.	Items	Goods in Nos.	Specification of Goods	Replaceable in nos.	Remarks
01	WC Commode	01			damaged.
02	Urinals	02	Boys: 01 Girls: 01		damaged
03	Doors	03 (Three)	Type: Steel/PVC/Wood (UPHAR) Size: 2'6" x 5' (W.C), 2'6" x 4' (2ND)		
04	Flooring		Tiles: Concrete: <input checked="" type="checkbox"/>		
05	Wall Level Flooring		Height: 2' Tile: <input checked="" type="checkbox"/> Concrete:		
06	Internal Plaster		CP: <input checked="" type="checkbox"/> Other:		
07	External Plaster		CP: <input checked="" type="checkbox"/> Other:		
08	Inspection Camber		Exists: Not-Exists: <input checked="" type="checkbox"/>		
9	Lease Pit/Septic Tank		Exists: <input checked="" type="checkbox"/> Not-Exists:		damaged
10	Electricity		Available: Not-Available: <input checked="" type="checkbox"/>		
11	Drainage System		Available: Not Available: <input checked="" type="checkbox"/>		

Sources of Water:  Well/ Well with pump/ Bore well with pump/ Hand pump or  Tube wellWater Tank:  Nil Concrete/PVC Overhead/Underground Tank Water Capacity:

Remarks or Suggestions if any: one boys toilets required.

Aswin Kanta Mahapatra

Sig. of School HM

Name:

Mb. No:

8908253004.

Sig. of SMC

Name:

Mb. No:

13/2/15

Sig. of TC

Name: Suranya Bahar

Technical Consultant  
Phulbani block  
RTE-SSA, Kandhamal

Sig. of Surveyor

Name:

D. Kela