

District: KANDHAMAL

Block: PHULBANI

Village: Landreju (Dadali GP)

Schools Name: Landreju PS

School Code: 21210903901

No. of students: 26

Boys: 16

Girls: 10

Status of Toilets: Exists/Non-Exists

No. of Boys Toilet: 1

No. of Girls Toilet: 1

1 - Common Toilet Damaged, 1 Common Toilet under construction
CWSN: under construction

No. of Toilets Required:

Boys: One

Girls:

Specification of Toilets:

Sl No.	Items	Goods in Nos.	Specification of Goods	Replaceable in nos.	Remarks
01	WC Commode	-			Damaged
02	Urinals	-	Boys: Girls:		
03	Doors	-	Type: Steel/ PVC/ Wood Size:		
04	Flooring	-	Tiles: Concrete: -		
05	Wall Level Flooring	-	Height: Tile: Concrete: -		
06	Internal Plaster		CP: - Other:		
07	External Plaster		CP: - Other:		
08	Inspection Camber		Exists: Not-Exists: ✓		
9	Lease Pit/Septic Tank		Exists: ✓ Not-Exists:		
10	Electricity		Available: Not-Available:		
11	Drainage System		Available: Not Available:		

Sources of Water: Well/Well with pump/Bore well with pump/Hand pump or Tube well

Water Tank: NA Concrete/PVC Overhead/Underground Tank Water Capacity:

Remarks or Suggestions if any: ONE Boys Toilet Required.

Sandy
13.2.15
Sig. of School HM

Pradeep Kumar Bagha
b. b. b. b. b.
Sig. of SMC

Sig. of TC

Sig. of Surveyor

Name: Sandhya Rani Mohanty

Name: 8895728678

Name: Guranya Kumar

Name: A. J. J.

Mb. No: 9439268787
Headmaster

Mb. No: 9439268787

Technical Consultant
Phulbani Block
RTE-SSA, Kandhamal

Landraju Primary School