

District: KANDHAMAL

Block: PHULBANI

Village:

Schools Name: <sup>U</sup>NAMARBALI N.P.S

School Code: 21210915901

No. of students: 26

Boys: 14

Girls: 12

Status of Toilets:  Exists/ Non-Exists

No. of Boys Toilet: 1+1

No. of Girls Toilet:

CWSN: one toilet under const<sup>n</sup>

No. of Toilets Required:

Boys: 1

Girls:

Specification of Toilets:

Sl No.	Items	Goods in Nos.	Specification of Goods	Replaceable in nos.	Remarks
01	WC Commode	2			damaged
02	Urinals		Boys: Girls:		
03	Doors		Type: Steel/ PVC/ Wood Size: 2x2'x6'		
04	Flooring		Tiles: Concrete: <input checked="" type="checkbox"/>		
05	Wall Level Flooring		Height: 8' Tile: Concrete: <input checked="" type="checkbox"/>		
06	Internal Plaster		CP: <input checked="" type="checkbox"/> Other:		
07	External Plaster		CP: <input checked="" type="checkbox"/> Other:		
08	Inspection Camber		Exists: Not-Exists: <input checked="" type="checkbox"/>		
9	Lease Pit/Septic Tank		Exists: Not-Exists: <input checked="" type="checkbox"/>		
10	Electricity		Available: Not-Available: <input checked="" type="checkbox"/>		
11	Drainage System		Available: Not Available: <input checked="" type="checkbox"/>		

Sources of Water: Well/Well with pump/Bore well with pump/Hand pump or Tube well

Water Tank:  Concrete/PVC  Overhead/ Underground Tank

Water Capacity: 500 litres.

Remarks or Suggestions if any: one number boys toilet required.

Signature of School HM

Namerbali N.P.S  
Phulbani Block

Mb. No: 8763588090

Signature of SMC

Sig. of SMC

Name:

Mb. No:

President  
S.E.C Namerbali N.P.S  
Phulbani Block

Signature of TC

Sig. of TC

Name: Bokanya Bahoo

Technical Consultant

Phulbani Block  
RTE-200, Phulbani Block

Signature of Surveyor

Name: