

District: KANDHAMAL

Block: PHULBANI MPL

Village:

Schools Name: <sup>SAHI</sup> ~~SAMPADAR~~ P.S

School Code: 21210907601

No. of students: 24

Boys: 12

Girls: 12

Status of Toilets:  Exists/Not Exists

Boys:

Girls:

CWSN: General Toilet

No. of Toilets Required:

Boys: 1

Girls:

Specification of Toilets:

Sl. No.	Items	Goods in Nos.	Specification of Goods	Replaceable in nos.	Remarks
01	WC Commode	1		1	1) good 2) damaged
02	Urinals		Boys: 1      Girls: 1		
03	Doors		Type: Steel/ PVC/ Wood Size: 3 x 2' x 6'		
04	Flooring		Tiles: <input checked="" type="checkbox"/> Concrete:		
05	Wall Level Flooring		Height: 7'      Tile: <input checked="" type="checkbox"/> Concrete:		
06	Internal Plaster		CCP: <input checked="" type="checkbox"/> Other:		
07	External Plaster		CCP: <input checked="" type="checkbox"/> Other:		
08	Inspection Camber		Exists:      Not-Exists: <input checked="" type="checkbox"/>		
9	Lease Pit/Septic Tank		Exists:      Not-Exists: <input checked="" type="checkbox"/>		
10	Electricity		Available:      Not-Available: <input checked="" type="checkbox"/>		
11	Drainage System		Available:      Not Available: <input checked="" type="checkbox"/>		

Sources of Water: Well/Well with pump/Bore well with pump/Hand pump or Tube well 

Water Tank: Concrete/Fiber      Overhead/Underground Tank      Water Capacity:

Remarks or Suggestions if any: one boys toilet

Sig. of School HM

Sig. of SMC

Sig. of TC

Sig. of Surveyor

Name: Saraswati Das

Name:

Name: Sukanya Bahoo

Name:

Mb. No: 9437529121

Mb. No:

g/c HEADMASTER  
Padarsahi Prry. School,  
Dist-Kandhamal

President  
S.M.C.  
Padarsahi Prry School

Technical Consultant  
Phulbani Block  
RTE-SSA, Kandhamal

A.K. Das