

District: KANDHAMAL

Block: PHULBANI

Village:

Schools Name: PAN GA PAJU P.S.

School Code: 21210916201

No. of students: 20

Boys: 8

Girls: 12

Status of Toilets:  Exists/ Non-Exists

No. of Boys Toilet: 1

No. of Girls Toilet: 1

CWSN:

No. of Toilets Required:

Boys: 1

Girls:

Specification of Toilets:

Sl No.	Items	Goods in Nos.	Specification of Goods	Replaceable in nos.	Remarks
01	WC Commode	1			
02	Urinals		Boys: 1 Girls: 1		
03	Doors		Type: <input checked="" type="checkbox"/> Steel/ <input checked="" type="checkbox"/> PVC/ <input checked="" type="checkbox"/> Wood Size: 2' x 6'		
04	Flooring		Tiles: <input checked="" type="checkbox"/> Concrete:		
05	Wall Level Flooring		Height: 7 Tile: <input checked="" type="checkbox"/> Concrete:		
06	Internal Plaster		CP: <input checked="" type="checkbox"/> Other:		
07	External Plaster		CP: <input checked="" type="checkbox"/> Other:		
08	Inspection Camber		Exists: Not-Exists:		
9	Lease Pit/Septic Tank		Exists: Not-Exists:		
10	Electricity		Available: Not-Available: <input checked="" type="checkbox"/>		nearly available
11	Drainage System		Available: Not Available: <input checked="" type="checkbox"/>		

Sources of Water: Well/Well with pump/<sup>Hand</sup>Bore well with pump/Hand pump or Tube well

Water Tank: Concrete/PVC Overhead/Underground Tank Water Capacity:

Remarks or Suggestions if any: One no boy's toilet require

prabhofe Nanda

Sig. of School HM

Name:

Mb. No: 9439249898

*Handwritten Signature*  
**HEAUMASIBA**  
 Panapalu Primary School

*Handwritten Signature*  
 Sig. of SMC

Name:

Mb. No:

*Handwritten Signature*  
 President  
 School Management Committee  
 Panapalu Primary School

Sig. of TC

Name: Sukanya Baboo

*Handwritten Signature*  
 Consultant  
 PHULBANI BLOCK  
 RTE-SSA, Kandhamal

Sig. of Surveyor

Name:

*Handwritten Signature*  
 A.K. Dasgupta