

11-02-15

District Tejpur Block Rasulpur Village Baliarposi
 School Name Baliarposi P.S. School Code 21130906301
 No. of Student Girls- Boys
 Status of toilet Existing
 Toilet Requirement Girls 01 Boys 00

If Existing:

Sl.No	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC	1 nos	
2	Urinals.	-	
3	Doors (size)	1x0.75x1.70	
4	Floor level	-0.900	
5	Wall level	1.95m.	
6	Internal plaster	Good	
7	Outer plaster	Good	
8	Inspection Chamber	1 nos -	
9	Lease pit / septic tank	-	

Source of Water

Bore well with pump /

Hand pump

(Water not usable).

Water tank

Ground /

Overhead

Water tank Capacity

Remarks if any:

~~One~~ Boys toilet exist. But no urinal for boys. One girls toilets is required. Separate urinal for boys is also required.

D. Naik

Sign of School head master

Sign of School Mgt Committee

Sign of Surveyor

Hedmaster
Baliarposi Primary School

Name Draupadi Naik

9438277319
 Name S.K. Padihi

9668421542

M.D.
08/11/15

LP
11/2/15