

District Tajpur Block Rasulpur Village Chandapur
 School Name Chandapur UPS School Code 21130907002
 No. of Student Girls- 67 Boys- 42
 Status of toilet Existing 01 Is it Existing
 Toilet Requirement Girls 01 Boys 0

If Existing:

Sl.No	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC	<u>1 nos.</u>	
2	Urinals.	<u>—</u>	
3	Doors (size)	<u>2x0.80x1.50</u>	
4	Floor level	<u>0.300</u>	
5	Wall level	<u>1.90</u>	
6	Internal plaster	<u>Good</u>	
7	Outer plaster	<u>Good</u>	
8	Inspection Chamber	<u>—</u>	
9	Lease pit / septic tank	<u>—</u>	

Source of Water

Bore well with pump /

Hand pump

Water tank

Ground /

Overhead

Water tank Capacity

Remarks if any:

Seeing the strength of students both toilets for boys & girls were required. Existing toilet not in use. New toilet can be constructed after demolishing the existing toilet.

to
 11.2.15
 Sign of School head master

Sign of School Mgt Committee

Sign of Surveyor

20 SUBAS CHANDRA PADHI.

MB-9937763675.

Name Headmaster

Chandpur U.P.School

Name

9438277319
 Name S.K. Parulhi

MB
 11/2/15

LP
 11/2/15