

11-02-15

A17

District **Jajpur** Block **Rasulpur** Village **Rasuna**
 School Name **Rasuna P.S.** School Code **2113091A001**
 No. of Student Girls- **35** Boys- **45**
 status of toilet Existing **1nos** Note Existing
 Toilet Requirement Girls **0** Boys **01**

If Existing:

Sl.No	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC	1nos	
2	Urinals	-	
3	Doors (size)	1.40 x 0.80	
4	Floor level	0.100	
5	Wall level	1.75	
6	Internal plaster	Good	
7	Outer plaster	Good	
8	Inspection Chamber	1 no	
9	Lease pit / septic tank	- Nil -	

Source of Water Bore well with pump / Hand pump Nil
 Water tank Ground / Overhead
 Water tank Capacity

Remarks if any: **As there is one WC. According to the strength of students both toilet for boys & girls are required.**

Sign of School head master

Sign of School Mgt Committee

Sign of Surveyor

Rasuna Primary School, Rasuna

Name **Bidulata Sahoo** Name

9438277319
Name **S.K. Paalhi**

9937111396

Handwritten signature

HP
11/2/15