

District - Dhenkanal Block :- Sadara. Village :- Balyamba.

School Name :- Balyamba U.P. School. School Code :-

No. of Student - 180 Girls - 86 Boys - 94

Status of toilet Existing Not Existing

Toilet Requirement Girls Boys

If Existing:

Sl.No	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC	02 not used	
2	Urinals	02 not used	
3	Doors (size)	✓	
4	Floor level	✓	
5	Wall level	✓	
6	Internal plaster	✓	
7	Outer plaster	✓	
8	Inspection Chamber	X	
9	Lease pit / septic tank	X	

Source of Water Bore well with pump / Hand pump 01

Water tank NA Ground / Overhead

Water tank Capacity NA

Remarks if any: Both toilet are ~~abandoned~~ abandoned. (Bad condition)
one toilet is under construction

Mohanty

Sign of School head master

Sign of School Mgt Committee

Ainul Huda
Sign of Surveyor

Name Namisamohanty. Name

Name AINUL HUDA

Mohanty
08/11/15

Ainul Huda
12/11/15