

District Dhenkanal Block Badan Village Tenua  
 School Name Tenua Primary School School Code 2407  
 No. of Student 34 Girls- 16 Boys- 18  
 Status of toilet Existing Not Existing  
 Toilet Requirement Girls Boys

If Existing:

Sl.No	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC	01	
2	Urinals	01	
3	Doors (size)	✓	
4	Floor level	✓	
5	Wall level	✓	
6	Internal plaster	✓	
7	Outer plaster	✓	
8	Inspection Chamber	✗	
9	Lease pit / septic tank	✓	

Source of Water Bore well with pump / Hand pump ✓  
 Water tank NA Ground / Overhead  
 Water tank Capacity NA

Remarks if any:

Purna ch Saha  
 Sign of School head master  
 (In charge)  
PURNA CHANDRA SAHA  
 Name

Sign of School Mgt Committee  
 Name

Saha  
 Sign of Surveyor  
 Name Biswajit Ku. Barik.

Saha  
08/11/15

Bm  
17/01/15