

District Dolanpur Block Sanjala Village Dumermunda
 School Name _____ School Code 21241211501
 No. of Student 56 Girls 36 Boys 20
 Status of toilet Existing Not Existing
 Toilet Requirement Girls Boys

If Existing:

Sl.No	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC	<input checked="" type="checkbox"/> (1)	<input checked="" type="checkbox"/>
2	Urinals	<input checked="" type="checkbox"/> (2)	<input checked="" type="checkbox"/>
3	Doors (size)	0.63X1.82	<input checked="" type="checkbox"/>
4	Floor level	1.0 1. P.S	<input checked="" type="checkbox"/>
5	Wall level	B/W	<input checked="" type="checkbox"/>
6	Internal plaster	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
7	Outer plaster	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
8	Inspection Chamber	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
9	Lease pit / septic tank	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

Source of Water Bore well with pump / Hand pump
 Water tank _____ Ground / Overhead
 Water tank Capacity X
 Electricity - Available / Not available.

Remarks if any: Requirement of girls toilet

[Signature]
 Headmaster
 Sign of School Headmaster
 DUMERMUNDA

[Signature]
 Sign of School Mgt Committee

[Signature]
 Sign of Surveyor

Name

Name

Name Sumantra Kumari
- Patel

[Signature]
08/11/15