

1597

District BOLANGIR Block SAINTALA Village Kadimunda
 School Name Kadimunda P-UPS School Code 212413013601
 No. of Student 52 Girls- 25 Boys- 27
 Status of toilet Existing Not Existing
 Toilet Requirement Girls Boys
 If Existing:

Sl.No	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC	X	✓ 1
2	Urinals	✓	X
3	Doors (size)	✓ 0.57 X 1.66	X
4	Floor level	X	✓
5	Wall level	X	✓
6	Internal plaster	X	✓
7	Outer plaster	X	✓
8	Inspection Chamber	X	✓
9	Lease pit / septic tank	X	✓

Source of Water Bore well with pump / Hand pump
 Water tank Ground / Overhead
 Water tank Capacity X
 Electricity Available / Not available

Remarks if any: It's was repair

Dharmeswar Nath
 Headmaster
 Primesy School
 Kadimunda
 Sign of School head master

President
 School Management Committee
 Sign of School Mgt Committee
 Kadimunda

[Signature]
 Sign of Surveyor

Name

Name Madhukaran

Name Sunamta Kumar Patel

[Signature]
 08/11/15