

1578

District Balaram Block Santala Village Suliamal  
 School Name Suliamal Govt. P.S School Code 21241212201  
 No. of Student 39 Girls- 19 Boys- 20  
 Status of toilet Existing Not Existing   
 Toilet Requirement Girls  Boys

If Existing:

Sl.No	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC	X	1
2	Urinals	X	2
3	Doors (size)	X	✓
4	Floor level	X	✓
5	Wall level	B/W	✓
6	Internal plaster	X	✓
7	Outer plaster	X	✓
8	Inspection Chamber	X	✓
9	Lease pit / septic tank	X	✓

Source of Water Bore well with pump / Hand pump   
 Water tank  Ground / Overhead  
 Water tank Capacity   
 Electricity - Available / Not available.

Remarks if any:  Girls toilet under const.  Required Boys toilet

Sign of School Headmaster  
 Govt. School  
 Suliamal

Sign of School Mgt Committee

Sign of Surveyor

Name Tapan Kumar Biswal

Name Sumantra Kumar Patel

Handwritten signature