

137

04
24-02-15

District Tejpur Block Sukinda Village Ragada
 School Name Ragada P.S. School Code 21131002401
 No. of Student Girls- 49 Boys- 53
 Status of toilet Existing 1 (boys) Not Existing
 Toilet Requirement Girls 01 Boys 0

If Existing:

| Sl.No | Item | Condition | |
|-------|-------------------------|--------------|------------------------|
| | | Good in Nos. | To be replaced in Nos. |
| 1 | WC | | <u>1 nos - Bad</u> |
| 2 | Urinals | | <u>-</u> |
| 3 | Doors (size) | | <u>-</u> |
| 4 | Floor level | | <u>0.200</u> |
| 5 | Wall level | | <u>1.68</u> |
| 6 | Internal plaster | | <u>Bad</u> |
| 7 | Outer plaster | | <u>Bad</u> |
| 8 | Inspection Chamber | | <u>-</u> |
| 9 | Lease pit / septic tank | | <u>-</u> |

Source of Water Bore well with pump Hand pump (Not working)
 Water tank Ground Overhead
 Water tank Capacity

Remarks if any: As the existing boys toilet is delapidated, hence both toilet for boys & girls are required.

[Signature]
 Sign of School head master
 V.E.C. Pr...

Sign of School Mgt Committee

[Signature]
 Sign of Surveyor
 24-02-15

Name Bhageshet Dehuri Name
9938426917

9938277319
 Name S.K. Pachi

[Signature]
 08/11/15

[Signature]
 24/2/15