

A39

05  
24-02-15

District Jajpur Block Sukinda Village Ransol 1  
 School Name Ransol P.S. School Code 21131009701  
 No. of Student Girls-19 Boys-16  
 status of toilet Existing 1 Boys Note Existing  
 Toilet Requirement Girls 01 Boys 0

If Existing:

Sl.No	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC	<u>1 nos -</u>	<u>1 nos -</u>
2	Urinals		<u>-</u>
3	Doors (size)		<u>1 x 0.60 x 1.68</u>
4	Floor level		<u>0.300</u>
5	Wall level		<u>1.82.</u>
6	Internal plaster		<u>Bed</u>
7	Outer plaster		<u>Bed -</u>
8	Inspection Chamber		<u>-</u>
9	Lease pit / septic tank		<u>1 no -</u>

Source of Water  Bore well with pump  Hand pump   
 Water tank  Ground  Overhead   
 Water tank Capacity

Remarks if any:

As the existing toilet is delapidated, hence both toilet for boys & girls are required.

Sign of School Headmaster

Sign of School Mgt Committee

Sign of Surveyor

Headmaster  
Ransol Primary School

Name Champa Soren

Name

9937860906

Name

S.K. Padhu.

12/15

12/15