


2/18



"स्वच्छ भारत अभियान"

DISTRICT: Balangir BLOCK: Swada VILLAGE: Gondagottha
 SCHOOL NAME: BAILAKHAMAN P.S. SCHOOL CODE:
 NO. OF STUDENT: 88 GIRLS: 45 BOYS: 43
 STATUS OF TOILET: EXISTING: (repair) NOT EXISTING:
 TOILET REQUIREMENT: GIRLS: BOYS:
 IF EXISTING: 1 Inflow under construction (1 WC + 1 urinal for girls)

5 5

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	/	1
2	URINALS		1 + 1
3	DOORS(SIZE)		✓
4	FLOOR LEVEL		✓
5	WALL LEVEL		✓
6	INTERNAL PLASTER		✓
7	OUTER PLASTER		✓
8	INSPECTION CHAMBER		
9	LEASE PIT/ SEPTIC TANK		✓

} require urgent repair

SOURCE OF WATER: BORE WELL WITH PUMP: HAND PUMP: 01

WATER TANK: GROUND: OVERHEAD:

WATER TANK CAPACITY:

Remarks If any:

- wiring done but no electricity yet
 - only source of water (01 handpump)

P. Gouda
 3-3-2015
 Sign of School Head Master

Swagat Das
 Sign of School Mgt Committee

Swagat Das
 3/3/15
 Sign of Surveyor

NAME: PRABHAKAR
GOUDA

NAME: DANIEL NAYAK NAME: SWAGAT DAS

(mob) 9178535566

Govt. Primary School
 Bailakhaman (Cmt)

CHAIRMAN
 School Management Commitee
 Bailakhamana, Gm.