

"स्वच्छ भारत अभियान"

DISTRICT: Ganjam BLOCK: Surada VILLAGE: Bandhagochha
SCHOOL NAME: Bandha Gochha SCHOOL CODE:
NO. OF STUDENT: 33 GIRLS: 17 BOYS: 16
STATUS OF TOILET: EXISTING: 1 NOT EXISTING:
TOILET REQUIREMENT: GIRLS: BOYS:
IF EXISTING:

SI. NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	1	
2	URINALS	-	2
3	DOORS(SIZE)	-	1 (25x40), 2 (25x40)
4	FLOOR LEVEL	2	1
5	WALL LEVEL	+	2
6	INTERNAL PLASTER	2	1
7	OUTER PLASTER	-	2
8	INSPECTION CHAMBER	-	-
9	LEASE PIT/ SEPTIC TANK	-	1

SOURCE OF WATER: BORE WELL WITH PUMP: - HAND PUMP: 1

WATER TANK: GROUND: - OVERHEAD: -

WATER TANK CAPACITY: -

Remarks If any: one block totally damage condition. was used by both

* - Electricity is not available (not even in village)

Sudarsan Sethi
Sign of School Head Master

Anil K. U. Sahai
Sign of School Mgt Committee

Shanthy
Sign of Surveyor 02/03

ANURIT
CREASTURRY

NAME: SUDARSAN SETHI NAME: ANIL KUMAR SAHAI NAME:

9937947125
Headmaster

9658471148

S. P. G. D. S.
21/11/15

Govt. Primary School
Bandhagochha (Gm.)

Sunil T.
Daigude