

186

Data as provided by CRCC
Could not be visited due to accessibility problems

Kidly
4/3/15

"स्वच्छ भारत अभियान" CRCC

DISTRICT: Ganjam

BLOCK: Surada

VILLAGE:

SCHOOL NAME: Ch. Saranath P.S.

SCHOOL CODE:

NO. OF STUDENT: 65

GIRLS: 35

BOYS: 30

STATUS OF TOILET:

EXISTING: X

NOT EXISTING: ✓

TOILET REQUIREMENT:

GIRLS: 1 WC + 1 Urinal

BOYS: 1 WC + 1 Urinal

IF EXISTING: - No existing toilets.

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	/	/
2	URINALS		
3	DOORS(SIZE)		
4	FLOOR LEVEL		
5	WALL LEVEL		
6	INTERNAL PLASTER		
7	OUTER PLASTER		
8	INSPECTION CHAMBER		
9	LEASE PIT/ SEPTIC TANK		

SOURCE OF WATER:

BORE WELL WITH PUMP:

HAND PUMP: 1

WATER TANK:

GROUND:

OVERHEAD:

WATER TANK CAPACITY:

Remarks If any:

- No electricity
- Handpump only source of water

Sign of School Head Master

Sign of School Mgt Committee

Signature
4/3/15
Sign of Surveyor

NAME:

Kalyan Chandra Sahoo
CRCC
CRC-Co-ordinator
Amrutulu Cluster
Surada Block (Gm)

NAME:

NAME: Swagat
Kumar Dahi