



major requirement of toilet infrastructure

"स्वच्छ भारत अभियान"

DISTRICT: Ganjam BLOCK: Surada VILLAGE: Goudagotha  
 SCHOOL NAME: GOUDAGOTHA P.S. SCHOOL CODE: 2119221540  
 NO. OF STUDENT: 274 GIRLS: 83 BOYS: 191  
 STATUS OF TOILET: EXISTING:  (totally damaged) NOT EXISTING:  
 TOILET REQUIREMENT: GIRLS: 2+2 BOYS: 4+2  
 IF EXISTING: (urinal/wc) (urinal/wc)

(4) - (12)

SI. NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	/	1+1
2	URINALS		1+1
3	DOORS(SIZE)		✓
4	FLOOR LEVEL		✓
5	WALL LEVEL		✓
6	INTERNAL PLASTER		✓
7	OUTER PLASTER		✓
8	INSPECTION CHAMBER		
9	LEASE PIT/ SEPTIC TANK		✓

SOURCE OF WATER: BORE WELL WITH PUMP:  HAND PUMP: 01  
 WATER TANK: GROUND:  OVERHEAD: (01) but dysfunctional

WATER TANK CAPACITY:

Remarks If any: - no electricity  
 - only source of water (1 handpump)

S.N. SETHY  
 Sign of School Head Master

ଶ୍ରୀମତୀ ସତ୍ୟା ନାରାୟଣ ସେଥୀ  
 Sign of School Mgt Committee

Swagat Das  
 Sign of Surveyor  
 MT(Enw)

NAME: SATYA NARAYAN SETHY

NAME: RASENTA  
 NIYAK

NAME: SWAGAT  
 DAS

9178862192  
 Headmaster  
 Govt. Primary School  
 Gaudagotha (Gm)

(Chairperson, SMC)