



"स्वच्छ भारत अभियान"

DISTRICT: Ganjam

BLOCK: Surada

VILLAGE: Gunduri badi

SCHOOL NAME: Gunduribadi P.S

SCHOOL CODE: 21192201301

NO. OF STUDENT: 20

GIRLS: -

BOYS: 20

STATUS OF TOILET:

EXISTING: X

NOT EXISTING: ✓

TOILET REQUIREMENT:

GIRLS: X

BOYS: 1+1

IF EXISTING: No toilet infrastructure. Funds have come for building toilets. Planning done.

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	/	/
2	URINALS		
3	DOORS(SIZE)		
4	FLOOR LEVEL		
5	WALL LEVEL		
6	INTERNAL PLASTER		
7	OUTER PLASTER		
8	INSPECTION CHAMBER		
9	LEASE PIT/ SEPTIC TANK		

SOURCE OF WATER:

BORE WELL WITH PUMP: X

HAND PUMP: 1

WATER TANK: X

GROUND: X

OVERHEAD:

WATER TANK CAPACITY:

Remarks If any: - No electricity  
- Handpump is the only source of water (water supply needed)

Sign of School Head Master

Sign of School Mgt Committee

Sign of Surveyor

NAME: PRABHATA KUMAR MAHANKUDA

NAME: ASHOK KUMAR PANDA (Member)

NAME: Swagat Kumar Dash

7077976624  
HEADMASTER  
PRIMARY SCHOOL  
GUNDURIBADI, GM