

"स्वच्छ भारत अभियान"

DISTRICT: Ganjam BLOCK: Surada VILLAGE: Genja
SCHOOL NAME: Kondha Bakhara S/S. SCHOOL CODE:
NO. OF STUDENT: 75 GIRLS: 38 BOYS: 37
STATUS OF TOILET: EXISTING: 1 NOT EXISTING:
TOILET REQUIREMENT: GIRLS: BOYS:
IF EXISTING:

SI. NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	1	
2	URINALS		2
3	DOORS(SIZE)		2 (65x20) 1 (72x25)
4	FLOOR LEVEL	1	2
5	WALL LEVEL	1	2
6	INTERNAL PLASTER	0/5	
7	OUTER PLASTER	0/5	
8	INSPECTION CHAMBER	0	-
9	LEASE PIT/ SEPTIC TANK	1	

SOURCE OF WATER: BORE WELL WITH PUMP: ✓ HAND PUMP: 1
WATER TANK: GROUND: OVERHEAD:
WATER TANK CAPACITY:

Remarks If any: ① Electricity not available
 ② One block in damage condition.

22.03.2015
 Sign of School Head Master
 KONDHA BAKHARA SEVASHRAM
 PO: GENJA, VIA: SURADA
 DIST: GANJAM
 NAME: Ramalal Chandra

CHAIRPERSON
 Sign of School Management Committee
 NAME: Binodhali

Sign of Surveyor
 NAME: AMRIT CHANDRAN
 21/3/15
 Sunil T. Dajgude