

"स्वच्छ भारत अभियान"

DISTRICT: Ganjam BLOCK: Surada VILLAGE: Lembhakumpa
SCHOOL NAME: Lembhakumpa P.S. SCHOOL CODE: 21192227951
NO. OF STUDENT: 60 GIRLS: 32 BOYS: 28
STATUS OF TOILET: EXISTING: 1 NOT EXISTING:
TOILET REQUIREMENT: GIRLS: BOYS:
IF EXISTING:

SI,NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	-	1
2	URINALS	-	1
3	DOORS(SIZE)	2(80" x 30")	
4	FLOOR LEVEL	105	1
5	WALL LEVEL	OK	(Roof damaged)
6	INTERNAL PLASTER	OK	
7	OUTER PLASTER	OK	
8	INSPECTION CHAMBER	-	
9	LEASE PIT/ SEPTIC TANK	1	

SOURCE OF WATER: BORE WELL WITH PUMP: - HAND PUMP: 1 (one)
WATER TANK: GROUND: - OVERHEAD: -
WATER TANK CAPACITY: -

Remarks if any: ① One block available but adjacent to the kitchen
 ② The block roof is damaged and need to be repair
 ③ No electricity

[Signature]
 Sign of School Head Master
 Govt. Primary School
 Lembhakumpa (Gm.)

[Signature]
 Sign of School Management Committee
 CHAIRPERSON -
 School Management Committee
 GOVT. P.S., Lembhakumpa (Gm.)

Sign of Surveyor

NAME:
 Kailas chandra Kapatra

NAME: Sumanchal Gouda

[Signature]
 4/3/15
 Sunil T.
 Dayguda