

Mob. No: 9438009592

208

"स्वच्छ भारत अभियान"

DISTRICT: Ganjam

BLOCK: Surada

VILLAGE: Gerja

SCHOOL NAME: Lunduriguda Project P.S.

SCHOOL CODE:

NO. OF STUDENT: 27

GIRLS: 10

BOYS: 17

STATUS OF TOILET:

EXISTING: 1 (1दिप)

NOT EXISTING:

TOILET REQUIREMENT:

GIRLS:

BOYS:

IF EXISTING:

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	1	1
2	URINALS	1	4
3	DOORS(SIZE)	1	2(25x25) 1(12x25)
4	FLOOR LEVEL	1	3
5	WALL LEVEL	1	3
6	INTERNAL PLASTER	1	3
7	OUTER PLASTER	1	3
8	INSPECTION CHAMBER	1	1
9	LEASE PIT/ SEPTIC TANK	1	1

SOURCE OF WATER:

BORE WELL WITH PUMP:

HAND PUMP: 1

WATER TANK:

GROUND: —

OVERHEAD: —

WATER TANK CAPACITY: —

Remarks If any: One block available but totally damaged & can't be used by any. No electricity

*[Signature]*  
Sign of School Head Master

**Headmaster**

**P.S. Lunduriguda (Gm)**

NAME: PABITRA KUMAR . NAME:

TRIPATHY

Asst. Tr.

*[Signature]*  
Sign of School Mgt Committee

*[Signature]*  
Sign of Surveyor

NAME: ANRIT

*[Signature]*  
21/15  
Sunil T.  
Dajwala