

152

5-7

School seal
unavailable during
survey

"स्वच्छ भारत अभियान"

DISTRICT: Ganjam BLOCK: Swada VILLAGE: Minajadi
SCHOOL NAME: Minajadi P.S SCHOOL CODE: 21192270601
NO. OF STUDENT: 19 GIRLS: 10 BOYS: 9
STATUS OF TOILET: EXISTING: ✓ NOT EXISTING:
TOILET REQUIREMENT: GIRLS: 1+1 BOYS: 1+1
IF EXISTING:

SI. NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC		1
2	URINALS		2
3	DOORS(SIZE)		✓
4	FLOOR LEVEL		✓
5	WALL LEVEL		✓
6	INTERNAL PLASTER		✓
7	OUTER PLASTER		✓
8	INSPECTION CHAMBER		✓
9	LEASE PIT/ SEPTIC TANK		✓

SOURCE OF WATER: ✓ BORE WELL WITH PUMP: ✗ HAND PUMP: ✗
WATER TANK: ✓ GROUND: ✗ OVERHEAD: ✗
WATER TANK CAPACITY:

Remarks If any: - No electricity
- No source of water supply

Sign of School Head Master Sign of School Mgt Committee Sign of Surveyor

NAME: Ajit Kumar Mallik NAME: Prasanto Mallik NAME: Swagati Kumar Das

8763669496
ପ୍ରଧାନ ଶିକ୍ଷକ
ଶିକ୍ଷକମାନଙ୍କ ସଂଘ
ଶିକ୍ଷକମାନଙ୍କ (ବିଭାଗୀୟ)