



231

"स्वच्छ भारत अभियान"DISTRICT: GanjamBLOCK: SurendaVILLAGE: PalakatuSCHOOL NAME: Nueagam P.S.SCHOOL CODE: 21192225002NO. OF STUDENT: 67GIRLS: 32BOYS: 35STATUS OF TOILET:EXISTING: 01 (3 chambers)NOT EXISTING:TOILET REQUIREMENT:GIRLS:BOYS:

IF EXISTING: 01 Mock 3 chambers - 1+3 - Urinal } Not functioning
2 - ur }
Another 1 Mock (3 chambers) is under construction.

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	1	Need repair
2	URINALS		1
3	DOORS(SIZE)		1
4	FLOOR LEVEL		1
5	WALL LEVEL		1
6	INTERNAL PLASTER		1
7	OUTER PLASTER		1
8	INSPECTION CHAMBER	Not existing	Need repair
9	LEASE PIT/ SEPTIC TANK	1	Need repair

SOURCE OF WATER: TubewellBORE WELL WITH PUMP: 1HAND PUMP: 01WATER TANK: 1GROUND: 1OVERHEAD: 1WATER TANK CAPACITY: 1

Remarks if any: Electricity not available in school, but available near school.

Sign of School Head Master

Sign of School Mgt Committee

Sign of Surveyor

NAME: Ranjanakupondrahi

NAME: Surendramini Mahapatra

NAME: SK Mohanty

Asst. teacher.

Nueagam p.s.

9938236500

P.N. 943825-1393

