

"स्वच्छ भारत अभियान"

DISTRICT: Ganjam

BLOCK: Surada

VILLAGE: ORA

SCHOOL NAME: Ora P.S.

SCHOOL CODE: 21192227501

NO. OF STUDENT: 36

GIRLS: 19

BOYS: 17

STATUS OF TOILET:

EXISTING: ① (B+G)

NOT EXISTING:

TOILET REQUIREMENT:

GIRLS:

BOYS:

IF EXISTING:

SI. NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	-	1
2	URINALS	-	4
3	DOORS(SIZE)	-	2(38"x25") 1(72"x25")
4	FLOOR LEVEL	2	1
5	WALL LEVEL	1	2
6	INTERNAL PLASTER	ok	
7	OUTER PLASTER	ok	
8	INSPECTION CHAMBER	-	1
9	LEASE PIT/ SEPTIC TANK	-	1

• School building unsafe (leakage) for the student

SOURCE OF WATER:

BORE WELL WITH PUMP: -

HAND PUMP: 1

WATER TANK:

GROUND: -

OVERHEAD: -

WATER TANK CAPACITY: -

Remarks If any: ① electricity not available


② One block-latrines damaged, unhas without pans, short height & without roof need to be repair for water

Durga Madhab Meher
Sign of School Head Master


Sign of School Mgt Committee

Sign of Surveyor

NAME:


M. Ramani
OVI. PRIMARY SCHOOL
ORA (GM.)

NAME: Hada Molik
Chairperson, SML
ORA Primary School
Surada (Gm)

NAME:


A/B/15

Sunil T.
Dajjale