

"स्वच्छ भारत अभियान"

DISTRICT: Ganjam

BLOCK: Surada

VILLAGE: Genja

SCHOOL NAME: Pangiapalli P.S.

SCHOOL CODE:

NO. OF STUDENT: 73

GIRLS: 34

BOYS: 39

STATUS OF TOILET:

EXISTING: 2 (1B+1G)

NOT EXISTING:

TOILET REQUIREMENT:

GIRLS: (2 di's functional repair require)

BOYS:

IF EXISTING:

SI. NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	2	
2	URINALS	6	3
3	DOORS(SIZE)	1(72x25) 1(57x36)	1(72x25) 2(57x25)
4	FLOOR LEVEL	2	3
5	WALL LEVEL	2	3
6	INTERNAL PLASTER	OK	
7	OUTER PLASTER	OK	
8	INSPECTION CHAMBER	-	2
9	LEASE PIT/ SEPTIC TANK	1	1

SOURCE OF WATER:

BORE WELL WITH PUMP: —

HAND PUMP: 1

WATER TANK:

GROUND: —

OVERHEAD: —

WATER TANK CAPACITY: —

Remarks If any: - Electricity available

- New building is being constructed for school and don't have a toilet facility in it

Mallick 2-3-15
Sign of School Head Master
Headmaster

କାଳିଚରଣ ପରିଡା
Sign of School Mgt Committee
Char Person

ANANT
Sign of Surveyor 2/3

Project Upper Primary School
for Pangia palli (Gull.)
NAME:

School Management Committee
P.S. Pangia Palli
NAME: KALICHARAN

CHANDHURY
NAME:

JAYANTI MALLICK

PARIDA

Signature
2/3/15

Surat T.
Dajude