



196  
5-6

"स्वच्छ भारत अभियान"

DISTRICT: Ganjam BLOCK: Surada VILLAGE: Asurabandha  
 SCHOOL NAME: Pani Amba PPS (Pani Amba)  
 NO. OF STUDENT: 56 GIRLS: 34 BOYS: 22  
 STATUS OF TOILET: EXISTING: NOT EXISTING:  
 TOILET REQUIREMENT: GIRLS: 1+1 BOYS: 1+1  
 IF EXISTING: No building. No toilet infrastructure

Sl.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	/	/
2	URINALS		
3	DOORS(SIZE)		
4	FLOOR LEVEL		
5	WALL LEVEL		
6	INTERNAL PLASTER		
7	OUTER PLASTER		
8	INSPECTION CHAMBER		
9	LEASE PIT/ SEPTIC TANK		

SOURCE OF WATER:  BORE WELL WITH PUMP:  HAND PUMP:   
 WATER TANK:  GROUND:  OVERHEAD:

WATER TANK CAPACITY:

Remarks If any: - No electricity (Urgent requirement for entire school infrastructure).  
 - No water supply  
 - School is functioning in a temporary hut.

Sign of School Head Master

Sign of School Mgt Committee  
 SIBA RAM SETHI

Sign of Surveyor  
 2/2/15

NAME: PURNACHANDRA NAYAK (Member) NAME: Swagat Kumar Dask  
 HEADMASTER N.P.S. Paniamba Surada (G.P.)  
 8763106356