

11

Sambalpur MP

ward no. 19

District Sambalpur Block Dhankeuda Village Badabazar

School Name Badabazar @ BOYS PS

School Code 21031401975

No. of Student 138

Girls- 62

Boys- 76

Status of toilet

Existing

Not Existing

Toilet Requirement

Girls

Boys

(NIL)

If Existing:

Sl.No	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC	1	
2	Urinals		2 NOS (need to be replaced)
3	Doors (size)		<input checked="" type="checkbox"/>
4	Floor level		,,
5	Wall level		10' / 5'
6	Internal plaster		,,
7	Outer plaster		,,
8	Inspection Chamber	NIL	
9	Lease pit / septic tank		

Source of Water

Bore well with pump /

Hand pump

(PHED)

Water tank

NIL

Ground /

Overhead

Water tank Capacity

Remarks if any:

Existing toilets and urinals need replacement urgently. Water supply should be provided to the toilets.

Sign of School head master

Sign of School Mgt Committee

Sign of Surveyor

Name Mishra

Name Kashinath Meher

Name A. Sahoo

7377704101

16.1.2015