


55



Sno - 565 / 55

"स्वच्छ भारत अभियान"

DISTRICT: Bhadrak BLOCK: Tangi VILLAGE: Ratanpur (Badhi Sahi)
 SCHOOL NAME: BADHISAHIL P.T. U.P.S SCHOOL CODE: 1017401
 NO. OF STUDENT: 176 GIRLS: 94 BOYS: 82
 STATUS OF TOILET: EXISTING: NOT EXISTING:
 TOILET REQUIREMENT: GIRLS: 02 BOYS: 02
 IF EXISTING: 1 set of toilet left half constructed (existing infra totally damaged)

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC		
2	URINALS		
3	DOORS(SIZE)		<u>totally damaged</u>
4	FLOOR LEVEL		<u>(unsuitable)</u>
5	WALL LEVEL		
6	INTERNAL PLASTER		
7	OUTER PLASTER		
8	INSPECTION CHAMBER		
9	LEASE PIT/ SEPTIC TANK		

SOURCE OF WATER: BORE WELL WITH PUMP: HAND PUMP: 01

WATER TANK: GROUND: OVERHEAD:

WATER TANK CAPACITY:
Remarks if any: - no electricity supply
- source of water (1 well + 1 handpump) within the premise

Dhr 28.11.15
Sign of School Head Master

ମିତାଲି ଜେନା ୨୮/୧୧/୨୦୧୫
Sign of School Mgt Committee

Swagat Das
28/11/15
Sign of Surveyor
M.T.(EW)

NAME: DWIJA BARBHUI NAME: MITALI JENA
Vice Chairperson, SMC

NAME: SWAGAT DAS
28/11/15
(688 Banda)

9090727263
Badhisahi P.T. School
At-Ratanpur, Kuhudi, Di-Khord...