

46

S no - 576/46



"स्वच्छ भारत अभियान"

DISTRICT: Khurda BLOCK: Tangi VILLAGE: Tangi
 SCHOOL NAME: BALARAM DEV BIDYAPITHA SCHOOL CODE: 1021801
 NO. OF STUDENT: 571 GIRLS: 215 BOYS: 356
 STATUS OF TOILET: EXISTING: NOT EXISTING:
 TOILET REQUIREMENT: GIRLS: BOYS:
 IF EXISTING: many damaged amenities infra str. exists (not in use anymore)

| SI.NO. | ITEM | CONDITION | |
|--------|------------------------|--------------|-------------------------------------|
| | | GOOD IN NOS. | TO BE REPLACED IN NOS. |
| 1 | WC | 1 no. | 3 nos |
| 2 | URINALS | 1 no. | 3 nos. |
| 3 | DOORS(SIZE) | / | <u>damaged</u> |
| 4 | FLOOR LEVEL | | <input checked="" type="checkbox"/> |
| 5 | WALL LEVEL | | <input checked="" type="checkbox"/> |
| 6 | INTERNAL PLASTER | | <input checked="" type="checkbox"/> |
| 7 | OUTER PLASTER | | <input checked="" type="checkbox"/> |
| 8 | INSPECTION CHAMBER | | |
| 9 | LEASE PIT/ SEPTIC TANK | | <input checked="" type="checkbox"/> |

SOURCE OF WATER: BORE WELL WITH PUMP: HAND PUMP: 2 (dysfunct.)
 WATER TANK: GROUND: OVERHEAD: 1 (damaged)

WATER TANK CAPACITY:
 Remarks if any: - major water problem (2 wells dysfunctional)
- electricity available (2 handpumps)

Signature
 Sign of School Head Master
Balaram Dev Bidyapitha
Tangi, Khurda

Signature
 Sign of School Mgt Committee

Signature
 Sign of Surveyor
MT (ew)

NAME: MANAS KDMAR
PARIDA.

NAME: Borajabandhu Das
9437754037

NAME: SWAGAT DAS
Signature
 27/1/15
 (S.S. Bando)

Mob: - 9861415117

MOB: S.M.C