


31

SNO - 532 / 31



"स्वच्छ भारत अभियान"

DISTRICT: Khurdha BLOCK: Tangi
 SCHOOL NAME: BRUNDABANPUR P.B.

VILLAGE: Brundabanpur
 SCHOOL CODE: 1013001

NO. OF STUDENT: 76 GIRLS: 44
 STATUS OF TOILET: EXISTING:
 TOILET REQUIREMENT: GIRLS:

BOYS: 34
 NOT EXISTING:
 BOYS:

If EXISTING:

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	2 nos.	
2	URINALS		01 (boys) - damaged
3	DOORS(SIZE)	/	
4	FLOOR LEVEL		✓
5	WALL LEVEL		✓
6	INTERNAL PLASTER		✓
7	OUTER PLASTER		✓
8	INSPECTION CHAMBER		-
9	LEASE PIT/ SEPTIC TANK		✓

SOURCE OF WATER: BORE WELL WITH PUMP: HAND PUMP: 01

WATER TANK: GROUND: OVERHEAD:

WATER TANK CAPACITY:

Remarks If any: - no electricity
- only source of water (1 handpump)

A. Majhi 27-01-15 Sign of School Head Master
 Suchitra Balabala 27-01-15 Sign of School Mgt Committee
 Swagat Das 27/01/15 Sign of Surveyor

NAME: ARATI MAJHI
 9937488507
 Headmaster
 Brundabanpur Primary School
 Date: _____

NAME: SUCHITRA BALABA
 NARYA
 (member), SMC

NAME: SWAGAT DAS
 (SS Panel)