


58



Sno - 540 / 58

"स्वच्छ भारत अभियान"

DISTRICT: Khordha BLOCK: Tangi

VILLAGE: Gopalprasad

SCHOOL NAME: DINABANDHUPUR P.B.

SCHOOL CODE: 1007301

NO. OF STUDENT: 79 GIRLS: 36

BOYS: 43

STATUS OF TOILET: EXISTING: X

NOT EXISTING: ✓

TOILET REQUIREMENT: GIRLS: 01

BOYS: 01

IF EXISTING: old toilet infra struct. completely damaged

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC		
2	URINALS		
3	DOORS(SIZE)		
4	FLOOR LEVEL		
5	WALL LEVEL		
6	INTERNAL PLASTER		
7	OUTER PLASTER		
8	INSPECTION CHAMBER		
9	LEASE PIT/ SEPTIC TANK		

SOURCE OF WATER:

BORE WELL WITH PUMP: X

HAND PUMP: 01

WATER TANK:

GROUND: X

OVERHEAD: X

WATER TANK CAPACITY:

Remarks if any: - no electricity supply
- only source of water (1 hand pump)

[Signature]
28/1/2015
Sign of School Head Master

[Signature]
Sign of School Mgt Committee

[Signature]
28/1/15
Sign of Surveyor
MT(emo)

NAME: BIDHUTI BHUSAN TUTHARSINGH

NAME: SHANTI PATRA NAME: SWAGAT DAS
member, SMC

(M) 9668010334
Headmaster
Dinabandhupur Primary School

[Signature]
28/1/15
CMA
(888kanda)