


18



Sno- 559/18

"स्वच्छ भारत अभियान"

DISTRICT: Khordha

BLOCK: Tangi

VILLAGE: Olasingh

SCHOOL NAME: GOVT. DABARATHI H.S.

SCHOOL CODE: 1015409

NO. OF STUDENT: 314

GIRLS: 138

BOYS: 176

STATUS OF TOILET:

EXISTING: ✓

NOT EXISTING:

TOILET REQUIREMENT:

GIRLS:

BOYS:

IF EXISTING: Girls (1 WC, 2 urinals)  
Boys (1 WC, 2 urinals)

SI.NO.	ITEM	CONDITION		
		GOOD IN NOS.	TO BE REPLACED IN NOS.	
1	WC	2	/	
2	URINALS	4		
3	DOORS(SIZE)	6 (6ft each)		
4	FLOOR LEVEL	✓		
5	WALL LEVEL	✓		
6	INTERNAL PLASTER	✓		
7	OUTER PLASTER	✓		
8	INSPECTION CHAMBER	X		✓
9	LEASE PIT/ SEPTIC TANK	✓		

SOURCE OF WATER:

BORE WELL WITH PUMP: X

HAND PUMP: 1 no.

WATER TANK:

GROUND: X

OVERHEAD: 1 no.

WATER TANK CAPACITY:

(over the school building)

Remarks If any:

- electricity supply available  
- no roof over the girls' urinal

Sign of School Head Master

Govt. Desbarathi High School  
Olasingh, Dist Khurda

NAME: NARENDRA KUMAR SWAIN

8895492935

Sign of School Mgt Committee

NAME: SABITA PRADHAN  
(member), SMC

Sign of Surveyor

NAME: SWAGATI DAS

(885 Panchayat only)