



6no - (327) / 7

"स्वच्छ भारत अभियान"

DISTRICT: Khordha

BLOCK: Tangi

VILLAGE: Belapada

SCHOOL NAME: JAGANNATHPUR PRIMARY SCHOOL

SCHOOL CODE: 1004502

NO. OF STUDENT: 39

GIRLS: 15

BOYS: 24

STATUS OF TOILET:

EXISTING: X

NOT EXISTING:

TOILET REQUIREMENT:

GIRLS: 01

BOYS: 01

IF EXISTING: completely damaged and dysfunctional toilet

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC		
2	URINALS		
3	DOORS(SIZE)		
4	FLOOR LEVEL		
5	WALL LEVEL		
6	INTERNAL PLASTER		
7	OUTER PLASTER		
8	INSPECTION CHAMBER		
9	LEASE PIT/ SEPTIC TANK		

SOURCE OF WATER:

BORE WELL WITH PUMP: X

HAND PUMP: 1 no.

WATER TANK:

GROUND: X

OVERHEAD: X

WATER TANK CAPACITY:

Remarks If any: - no electricity supply  
- only source of water (partially functional hand pump)

*Minaketan Das*  
25/11/15  
Sign of School Head Master

*Pandava Tada*  
Sign of School Mgt Committee

*Swagat Das*  
25/11/15  
Sign of Surveyor  
MT (EW)

NAME: MINAKETAN DAS  
Headmaster  
Jagannathpur Pvy. School

NAME: PANDAVA  
TADA  
(Member), SMC

NAME: SWAGAT DAS  
*Swagat Das*  
(Assistant)  
C.M.O.

9777358626