



Sno - 545 / 66

"स्वच्छ भारत अभियान"

DISTRICT: Khordha BLOCK: Tangi VILLAGE: Kunjuri
SCHOOL NAME: KUNJURI P.S. SCHOOL CODE: 1008901
NO. OF STUDENT: 56 GIRLS: 27 BOYS: 29
STATUS OF TOILET: EXISTING: ✓ NOT EXISTING: X
TOILET REQUIREMENT: GIRLS: BOYS:
IF EXISTING: main persisting problem - no electricity supply

SI.NO.	ITEM	CONDITION		
		GOOD IN NOS.	TO BE REPLACED IN NOS.	
1	WC	2 nos.	/	
2	URINALS	2 nos.		
3	DOORS(SIZE)	✓		
4	FLOOR LEVEL	✓		
5	WALL LEVEL	-		
6	INTERNAL PLASTER	-		✓
7	OUTER PLASTER	-		✓
8	INSPECTION CHAMBER	-		
9	LEASE PIT/ SEPTIC TANK	-		✓

SOURCE OF WATER: BORE WELL WITH PUMP: X HAND PUMP: 1

WATER TANK: GROUND: X OVERHEAD: 1

WATER TANK CAPACITY: 600 tts

Remarks if any: water sourced from (handpump + govt. panchayat water supply) motor arranged but lack of electricity supply for overhead tank usage

Sign of School Head Master
BSEH
 29.1.15

Sign of School Mgt Committee
 Umamani Pradhan
 29.1.2015

Sign of Surveyor
 Swagat Das
 29/01/15
 MT(EM)

NAME: BALAVADRASETHY NAME: UMAMANI PRADHAN NAME: SWAGAT DAS
 9777304428 (member) GMC

Headmaster
 Kunjuri Primary Sch